UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

Or
Land Survey Monuments situated in Section
(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)
Monument Description and Remarks: <u>Found 1" pipe with 60D nail and 5/8" rebar on S. side 12" deep.</u> Accepted position. Previous ties altered or obliterated.
This Corner was used for a Plat of Survey, Lot 1 of Parcel B, in the NW 1/4 of the NE 1/4 of Section 21.
PLAN VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will

21 21

GATE POST
S. SIDE ENTRANCE

O

30.36

Found 1" pipe with 60D nail and 5/8" rebar on S. side of pipe, 12" deep.

Q ILL. Dr.

46.64

POWER POLE

EXIST. "X" NAILS POWER POLE

NE Cor., NW 1/4 of the NE 1/4, Section 21

Date of Survey: 11/19/21 NOTE:

enable recovery of the corner.)

NOTE: ALL TIES TO YELLOW/ORANGE PLASTIC SURVEY MARKER UNLESS NOTED.

J.BRIAN MORRISSEY 895

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly Licensed Land Surveyor under the laws of the state of lowa.

Signature: J. Brian Morrissey

License number 7995.

My license renewal date is December 31, 2023

1140-21-1/4

Date: 2/16/22